

EYE AND FACE PROTECTION LIST



TASK	SAFETY GLASSES	GOGGLES / SEALED SAFETY GLASSES	FACE SHIELD OR WELDING HOOD	NOTES
Use of Right Angle Grinder – Cut/Grind		X	X	
Use of a Die Grinder		X	X	
Use of a Metal Cutting Circular Saw		X	X	
Overhead Drilling/Cutting		X	X	Drilling/ cutting above shoulder height.
Use of Compressed Air for Cleaning		X	X	Consider respiratory protection based on material (e.g., silica).
Welding Slag Removal	X		X	
Cad/Exothermic Welding	X		X	Shade 5 minimum.
Torch Cutting	X		X	Shade 5 minimum.
Pouring Concrete (at discharge of chute/hose)	X		X	Wire mesh face shield approved.
Vibrating Concrete	X		X	Wire mesh face shield approved.
Use of Demo/Chop Saw (concrete/metal)	X		X	
Concrete Surface Prep - Chipping, Scabbling, Bush Hammering	X		X	
Use of Jackhammer	X		X	
Use of Chain Saw	X		X	Wire mesh face shield approved.
Weed Eating	X		X	Wire mesh face shield approved.
Pressure Washing	X		X	
Use of Pneumatic Fastening Tool	X		X	
Use of Powder Actuated Tool	X		X	

NOTE 1: The above list contains examples of work activities to guide the worker in proper eye/face selection. Additional information will be available in task specific JHAs.

NOTE 2: Sealed safety glasses are safety glasses equipped with a foam or rubber seal that forms a seal between the safety glasses and the workers face.

NOTE 3: Where respiratory protection is required, an approved full-face respirator/powerd air-purifying respirator (PAPR) will meet the requirement for face protection.

Approved by:

Kieran Kelly
BNI ES&H Manager

03/12/21

RC-UPF DMC
03/30/21 15:01